
OVERHAUL - W4A020 & W4A040

RB Tech 1830 S. Figueroa street LA, Ca 90015 213 747-5800 Fig. 8: Assembled View Of Valve Body & Damper Housing MERCEDES-BENZ OF NORTH AMERICA. 1992 Mercedes-Benz 500E




- Reed-Type Check Valve (With Bore)
 Primary Pump Check Valve
 Control Pressure Regulating
 Valve Plunger
 Valve Body Housing
 Brake Band B-2 Shift
 Valve Strainer

- 6. Damper Housing 7. Range (Gear) Selector Valve
- 8. Drain Valve (Some Models)


OVERHAUL - W4A020 & W4A040

RB Tech 1830 S. Figueroa street LA, Ca 90015 213 747-5800 Fig. 9: Exploded View Of Valve Body (Check Ball & Check Valve Locations)
MERCEDES-BENZ OF NORTH AMERICA.
1992 Mercedes-Benz 500E




RB Tech 1830 S. Figueroa street LA, Ca 90015 213 747-5800

Fig. 10: Exploded View Of Valve Body MERCEDES-BENZ OF NORTH AMERICA. 1992 Mercedes-Benz 500E



RB Tech 1830 S. Figueroa street LA, Ca 90015 213 747-5800 Fig. 11: Exploded View Of Damper Housing MERCEDES-BENZ OF NORTH AMERICA. 1992 Mercedes-Benz 500E



- Damper Housing
 Pressure Limiting Valve
 Clutch K-1 Damper
 Control Valve

- 5. Brake Band B-1 Damper 6. Brake Band B-1 Damper Control Valve 7. Deceleration (Fuel Cut-Off) Shift Valve 93G24840

- 8. Modulating Pressure Valve 9. Lubricating Pressure Valve 10. Reverse (RV1) Shut-Off Valve
- 11. Braking Shift Shut-Off Valve 12. Kickdown Damper 13. Clutch K-2 Shift Valve

- 14. Brake Band B-2 Detent Valve
- 15. Damper (Cut-In) Switching Control Valve 16. Reverse (RV2) Shut-Off Valve 17. Damper (Cut-In) Switching Valve 18. Clutch K-2 Damper

- 19. Shift Pressure Control Valve 20. Clutch K-2 Damper Control Valve

1983-94 AUTOMATIC TRANSMISSION OVERHAUL Mercedes-Benz W4A020 & W4A040

500E SHIFT SPEEDS - SHIFT LEVER IN "D"

Application	МРН
Full Throttle	
1-2 Upshift	29
2-3 Upshift	65
3-4 Upshift	102
4-3 Downshift	71
3-2 Downshift	25
2-1 Downshift	15
Kickdown	
1-2 Upshift	42
2-3 Upshift	70
3-4 Upshift	106
4-3 Downshift	96
3-2 Downshift	58
2-1 Downshift	24

RB Tech	\$ 6 6	213 747-5800
Sunday, January 25, 2009 4:49:47 PM	Page 1 © 2005	Mitchell Repair Information Company, LLC.

BRAKE SYSTEM 1992 BRAKES Mercedes-Benz Disc

DISC BRAKE SPECIFICATIONS

DISC BRAKE SPECIFICATIONS

Application	In. (mm
Disc Diameter	
Front	11.8 (300)
Rear	10.9 (278
Lateral Runout	
Front	.005 (.12
Rear	.006 (.15
Parallelism	.0008 (.020
Disc Thickness	
Standard	
Front	1.10 (28
Rear	.94 (24
Minimum Refinish Thickness	
Front	1.02 (26
Rear	.87 (22
Wear Limit	
Rear	1.00 (25.4
Front	.84 (21.4
Caliper Piston Diameter	(1
Caliper Piston Bore Diameter (2)	
Fixed Caliper Front Axle (Teves Caliper)	
Top	1.495-1.497 (37.98
	38.03
Bottom	1.653-1.655 (41.98
	42.03
Fixed Caliper Rear Axle (Bendix ATE 38)	1.496-1.497 (37.99-38.03
Floating Caliper Front Axle (Teves Or Girling)	2.126-2.128 (54.00-54.05
Inside Diameter For Parking Brake	6.5 (164

⁽²⁾ Bore diameter at outer section may be exceeded by up to .004" (.1 mm) by polishing with emery cloth for repair.

RB Tech	213 747-580
Sunday, January 25, 2009 4:52:00 PM	Page 1 © 2005 Mitchell Repair Information Company, LL0

ELECTRONIC ACCELERATOR CONTROL MODULE REPLACEMENT

ELECTRONIC ACCELERATOR CONTROL MODULE REPLACEMENT

TECHNICAL SERVICE BULLETIN

Reference Number(s): 30/4, Date of Issue: June 1992

ENGINE 104.990, 119.970/971/974/975 WITH ASR - REPLACEMENT OF ELECTRONIC ACCELERATOR CONTROL MODULE

Model(s): 1992 Mercedes-Benz 400 E, 500 E, 300 SE, 400 SE, 500 SEL

Group: 30 - Accelerator Control, Cruise Control (CC), Electronic Accelerator (EA)

Bulletin No.: 30/4

Date: June 1992

SERVICE INFORMATION

The Electronic Accelerator control module (used on cars with ASR) must be replaced in vehicles that fall within the range of engine numbers listed below. Always check with the Vehicle Master Inquiry to determine if the work needs to be done on a specific vehicle. The affected control modules contain software that may be too sensitive to certain conditions, resulting in the ASR warning lamp lighting, or the Electronic Accelerator system entering "limp-home" mode, combined with the storage of false failure codes. The codes tend to be related to the Electronic Accelerator actuator and the CAN-bus, but are not always consistent.

EFFECTIVE SERIAL NUMBER RANGE

Model	From Engine Number	To Engine Number	From Chassis End Number (approx.)	To Chassis End Number
124.034	001700	003506	702384	772481
124.036	003064	004325	704685	768187
140.032	023667	033017	054960	079682
140.042	006478	009154	054800	079062
140.051	013544	019258	053809	079448

The new control modules have a production date of 16/92 (week 16 of 1992) or later stamped in blue. An additional way to identify the new modules is to check the "K" number, (circled in Fig. Fig. 1.)

"K"-NUMBER LEVEL

Model	Sales Designation	"K"-number must be:
124.034	400 E	K11 or greater
124.036	500 E	K10 or greater
140.032	300 SE	K12 or greater
140.042	400 SE	K10 or greater

RB Tech		213 747-5800
Sunday, January 25, 2009 4:55:06 PM	Page 1	© 2005 Mitchell Repair Information Company, LLC.

ELECTRONIC ACCELERATOR CONTROL MODULE REPLACEMENT

140.051	500 SEL	K10 or greater
1140.031	JOO OLL	1110 01 61 vater1

Vehicles that are in for service should be checked to determine if the new control module has been installed. If not, the new module should be installed according to the following chart. Customers whose vehicles are not scheduled for service in the very near future should be contacted and asked to bring their vehicles in specifically for this purpose.

PARTS INFORMATION

PARTS INFORMATION

Qty.	Part Name	Model Application	Part Number
1	Electronic Accelerator control module	124.034	124 545 06 32
1	Electronic Accelerator control module	124.036	124 545 07 32
1	Electronic Accelerator control module	140.032	140 545 65 32
1	Electronic Accelerator control module	140.042	140 545 14 32
1	Electronic Accelerator control module	140.051	140 545 15 32

CAUTION: The ignition must be turned OFF whenever an Electronic Accelerator Control Module (N4/1) is removed or installed. After control module installation:

- The shift selector lever must be in position P or N.
- The ignition switch must be turned ON for 90 seconds (without starting the engine). This allows the synchronization of the Electronic Accelerator Control Module (N4/1) and the Electronic Accelerator Actuator (M16/1) to take place.
- After the 90 second synchronization period, the ignition switch must be turned OFF.

WARRANTY CLAIM SUBMISSION INFORMATION

Submit a "Repair type 3" Warranty claim with applicable Repair code.

WARRANTY INFORMATION

Campaign No	Damage Code	Repair Code (1)	Time (hrs.)
92-0441	54960 19	10	0.2 hr.
11	! †	11	0.3 hr.


(1) - Operation: Check production date of Electronic Accelerator Control Module, if found to be OK (Repair code 10).

Check production date of Electronic Accelerator Control Module and replace (Repair code 11).

Sunday, January 25, 2009 4:55:00 PM	Page 2 ©	2005 Mitchell Repair Information Company, LLC.
RB Tech		213 747-5800

ELECTRONIC ACCELERATOR CONTROL MODULE REPLACEMENT

Only ONE repair code applies.



98C55790

Fig. 1: Electronic Accelerator Control Module Identification Sticker (Located On Side Of Module)

RB Tech	**************************************	213 747-5800
Sunday, January 25, 2009 4:55:00 PM	Page 3 © 2005 N	litchell Repair Information Company, LLC.