

MODEL 123, 124, 126, 201

Damage Code	Cause	Remedy	
No Code	Spring core in seat cushion frame too soft.	<p>1 Model 123</p> <p>- Install three additional foam blocks, part no. 123 920 15 66. Model 126 vehicles without electric rear seat adjustment can also be reinforced subsequently.</p> <p>Model 124</p> <p>- Install three additional foam blocks, part no. 124 920 00 66.</p> <p>Model 201</p> <p>- Install two additional foam blocks, part no. 201 920 00 66 and one foam block, part no. 201 920 01 66.</p>	

Teile-Bestell-Hinweise

Teil-Nr.	Designation	Anzahl
123 920 15 66	Additional foam blocks (Model 123)	3
124 920 00 66	Additional foam blocks (Model 124)	3
201 920 00 66	Additional foam blocks (Model 201)	2
201 920 01 66	Foam block (Model 201)	1