

Between 07 89 and 09 89 and from 06 90 the dampers for the tensioner have vulcanized lower rubber bearings.

- A Pressed-on rubber bearing
- B Vulcanized rubber bearing

