


TRANSMISSION 722.3 in MODEL 107, 124, 126, 129, 140, 201, 210

TRANSMISSION 722.4 in MODEL 124, 126, 129, 140, 201, 202, 210

TRANSMISSION 722.5 in MODEL 124, 129, 140, 210

Revisions

26.8.98	Validity updated		
---------	------------------	--	--

Damage code	Cause	Remedy	
27 282 35	Friction variations on brake band B2	1 Change oil in transmission  Drain 5 liters of oil only and add 5 liters of new oil. The percentage of new oil should only be approx. 70 %. Automatic transmission fluid with part no. 001 989 07 03/11 should no longer be used.	

Service products for repair

Part no.	Designation	Quantity
001 989 23 03/11	AT fluid	