

0/09/2001 CATHY
11:21:13

ISTRINGHAUSEN IMPORTS, INC.
(28) USED MERCEDES INV 10/09/2001

0519
PAGE 1

DATE	REFERENCE	DESCRIPTION	UNL#	ACCOUNT	DETAIL	240	240M	240S	311K	DAYS
	#795271	192 MERCEDES BENZ 500 (WDBEA36E1NB795271)								
06/99	17137	WALKER CONSIGNMENT	11	240	45000.00					859
07/15	22359	GREENSPORT	06	240	1401.20					317
07/27	727201	BETA	11	240	125.00					305
09/30	30818	RBM OF ATL	06	240	4514.38					740
10/29	41897	RBM OF ATL	09	240	789.67					711
04/10	04403	LAURENT DE GIVE CO	06	240	795.42					547
06/30	MBI54083	PARTS TICKET	04	240	476.25					466
07/28	06660	LAURENT DE GIVE	06	240	1432.26					433
08/15	MBI58326	GI-LUBE	03	240	40.70					423
	9									
08/31	MBR56938	PARTS TICKET	04	240	70.75					401
	A									
08/31	3232	PO# 3232 Automatic	09	240	1648.60					404
		A/M BILL								
12/15	39378	LAURENT DE GIVE	06	240	4296.59					298

09/05	MBI63234	PARTS FOR BRAKES	04	240	409.09					341
		TOTAL								

sent to Di Br...

18999.91

* might be to do w/ temp being too hot

INVOICE

Rennsport

ALLOY WHEEL POLISHING, PAINTING & REPAIR
10390 ALPHARETTA STREET, SUITE 620
ROSWELL, GEORGIA 30075
(770) 992-9442

DATE	INVOICE #
7/12/99	19423

BILL TO:
ISRINGHAUSEN IMPORTS OF DEC.
229 EAST JEFFERSON
SPRINGFIELD, ILLINOIS 62701

file MB 795271

P.O. NUMBER	TERMS	PROJECT
	Net 10	

Att. Cashier

QUANTITY	DESCRIPTION	RATE	AMOUNT
3	RIM REPAIR 17'	108.00	324.00
4	CUSTOM PAINT W/CLEAR COAT	60.00	240.00
4	DUNLOP SP8000 245-45-17	184.80	739.20
4	GEORGIA SCRAP TIRE FEE	1.00	4.00
4	TIRE DISPOSAL	1.00	4.00
4	DISMOUNT, REMOUNT, BALANCE TIRE	15.00	60.00
20	PAINT LUG NUT	1.50	30.00
		TOTAL	\$1,401.20

*93 ~~EE~~
1500
160*

*Walker
T.I.*

795271

45000

EB0

61397

31406



RBM OF ATLANTA
7640 Roswell Road
Atlanta, Georgia 30360
(770) 390-0600

INVOICE

Mercedes-Benz

PAUL ISRINGHAUSEN
229 EAST JEFFERSON
SPRINGFIELD, IL 62761
HOME: 404-229-8229 BUS: 800-790-1340

PAGE 1

SERVICE ADVISOR: 414 RONALD C TONA

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG, DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., PAYMENT, INV DATE. Includes vehicle details for a 1992 Mercedes 500E.

Main repair invoice table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various services like oil change, wiper replacement, and brake fluid service.

STATEMENT OF DISCLAIMER

LIMITED WARRANTY

The only warranties applying to the part(s) installed in accordance with this repair order are those that may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties including any implied warranty of merchantability or fitness for a particular purpose.

Summary table with columns: DESCRIPTION, TOTALS. Rows include LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS, SALES TAX, and PLEASE PAY THIS AMOUNT.

CUSTOMER COPY

61397

31406

INVOICE



Mercedes-Benz

RBM OF ATLANTA
7640 Roswell Road
Atlanta, Georgia 30350
(770) 390-0600

PAUL ISRINGHAUSEN
229 EAST JEFFERSON
SPRINGFIELD, IL 62701
HOME: 404-229-8229 BUS: 800-790-1340

PAGE 2

SERVICE ADVISOR: 414 RONALD C TONA

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, L CENSE, MILEAGE IN/OUT, TAG, DEL DATE, FROM DATE, WARR. EXP., PROMISED, PO NO., PAYMENT, INV DATE. Includes details for 1992 Mercedes 500E.

Table with columns: LINE, CPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various parts and labor items such as GASKET, TRANS, PLUG, BRAKE FLUID, BUSHING, BRAK, WIPER BLADE, FLEXABLE JOI, etc.

458110 STEERING LOCK KEY CYLINDER, REPL.
PARTS: 1209.75 LABOR: 789.68 OTHER: 0.00 TOTAL LINE A: 1999.43

B STEAM CLEANED ENGINE COMPARTMENT AND DRIVETRAIN, CHANGED DIFFERENTIAL LUBE, POWER STEERING FLUID AND FILTER.
STM+ STEAM CLEANED ENGINE COMPARTMENT AND DRIVETRAIN, CHANGED DIFFERENTIAL LUBE, POWER STEERING FLUID AND FILTER.

Table with columns: LINE, CPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists parts like FILTER, P/S, GASKET, P/S FLUID.

PARTS: 20.11 LABOR: 52.50 OTHER: 0.00 TOTAL LINE B: 72.61

STATEMENT OF DISCLAIMER and LIMITED WARRANTY table with columns: DESCRIPTION, TOTALS. Includes rows for LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS, SALES TAX, PLEASE PAY THIS AMOUNT.

CUSTOMER COPY

61397

3 1 4 0 6



7640 Roswell Road
Atlanta, Georgia 30350
(770) 390-0600

INVOICE

Mercedes-Benz

PAUL ISRINGHAUSEN
229 EAST JEFFERSON
SPRINGFIELD, IL 62701
HOME: 404-229-8223 BUS: 800-790-1340

PAGE 3

SERVICE ADVISOR: 414 RONALD C TONA

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
139/275	1992	MERCEDES 500E	WDBEA36E1NB79527		92423/92693	TRONT
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	PAYMENT	INV. DATE
20JUL1992	12MAR98	19JUL1996	17:30 15SEP99		CASH	30SEP1999
R.O. OPENED		READY	OPTIONS: DLR:36112 ENG:19974120C5031 TRN:737351 1)124036.1B.795271 2)RAD:9167 C9717865			
11:05 02JUN99	10:06 30SEP99					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
C THE SHIFTER IS LOOSE							
27000001				REPLACE SHIFTER BUSHINGS		78.75	78.75
				470 CC 1.50			
2	115-992-03-10			BUSHING	3.00	3.00	6.00
PARTS:	6.00	LABOR:	78.75	OTHER:	0.00	TOTAL LINE C:	84.75

D THE LEFT FRONT DOOR WILL POP WHEN OPENED.							
722701				REPLACE LEFT FRONT DOOR CHECK STRAP		77.83	77.83
				470 CC 1.10			
1	26-720-05-116			DOOR CHECK	21.45	21.45	21.45
PARTS:	21.45	LABOR:	77.83	OTHER:	0.00	TOTAL LINE D:	99.28

E LIGHT OUT INDICATOR LIGHT IS ON							
N NO WORK PERFORMED AT THIS TIME							
				470 CC 0.00			(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE E:	0.00

F THE LIGHT SWITCH CONTROL KNOB IS MISSING--REPLACE.							
D DONE							
				470 CC 0.00		0.00	0.00
1	202-545-00-81			KNOB	4.20	4.20	4.20
PARTS:	4.20	LABOR:	0.00	OTHER:	0.00	TOTAL LINE F:	4.20

G CHECK OVER FOR ANY FLUID LEAKS, ADVISE							
352500				REAR AXLE CENTER PIECE R & R		339.60	339.60
				70 CC 4.80			
351258				REAR AXLE CENTER PIECE SEAL RING - LEFT & RIGHT SIDE, REPL.		56.60	56.60
				70 CC 0.80			
354500				REAR AXLE CENTER PIECE FRONT SEAL, REPL.			

STATEMENT OF DISCLAIMER

LIMITED WARRANTY

The only warranties applying to the part(s) installed in accordance with this repair order are those that may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties including any implied warranty of merchantability or fitness for a particular purpose. No employee of the seller is authorized to alter or modify in any way any provisions of this disclaimer.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

Oct 16 01 11:02a
09/30/1999 12:53

Paul E. Isringhausen
7703996394

RBM OF ATLANTA

404-531-0072

PAGE 05/07

p.7

61397

31406



RBM
OF ATLANTA

7640 Roswell Road
Atlanta, Georgia 30350
(770) 390-0800

INVOICE

Mercedes-Benz

PAUL ISRINGHAUSEN
229 EAST JEFFERSON
SPRINGFIELD, IL 62701
HOME: 404-229-8229 BUS: 800-790-1340

PAGE 4

SERVICE ADVISOR: 414 RONALD C TONA

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG	
199/275	1992	MERCEDES 500E	WDBEA36E NB795271		92423/92593	FRONT	
DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	PAYMENT	INV DATE	
20JUL1992	12MAR96	19JUL1996	17:30 15SEP99		CASH	30SEP1999	
R.O. OPENED	READY	OPTIONS: DLR:36112 ENG:11997412005031 TRN:737351					
11:05 02JUN99	10:06 30SEP99	1)124036.13.795271 2)RAD:9167 C9717865					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
				70 CC		240.55	240.55
35000201				ADDITIONAL TIME TO REMOVE RUST FROM ABS			
				HOLES IN DIFF HOESING			
				70 CC	0.80	56.60	56.60
2	014-997-97-48			SEAL RING.RE	3.60	3.60	7.20
1	014-997-97-48			SEAL RING.RE	3.60	3.60	3.60
2	014-997-72-47			SEAL RING.VL	19.25	19.25	38.50
	123-353-00-72			NUT	3.74	3.74	3.74
	124-350-03-90			BREATHER,AXL	57.10	57.10	57.10
	LUBE 3.0 PTS. DIFF. FLUID					5.85	5.85
PARTS:	120.14	LABOR:	693.35	OTHER:	5.85	TOTAL LINE G:	819.34

 H HAVE THE DENTS REMOVED ALL OVER *** SUBLET ***.
 S SUBLET REPAIRS.
 414 T 0.00 (N/C)
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H: 0.00

I** THERE IS A HESITATION WHEN ACCELERATING, ADVISE
 CAUSE: RSS
 006473 AUTOM. TRANSM. OIL WITH FILTER, CHANGE
 412 CC 1.30
 2 001-989-23-03-11 TRANS. FLUID 83.60 83.60 167.20
 PARTS: 157.20 LABOR: 91.98 OTHER: 0.00 TOTAL LINE I: 259.18

J** THE CLIENT HAS HAD TO ADD OIL BETWEEN SERVICES, ADVISE
 CAUSE: RSS
 N. NO. WORK PERFORMED AT THIS TIME
 412 CD 0.00
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE J: 0.00

STATEMENT OF DISCLAIMER

LIMITED WARRANTY

The only warranties applying to the part(s) installed in accordance with this repair order are those that may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties including any implied warranty of merchantability or fitness for a particular purpose. No employee of the seller is authorized to alter or modify in any way any provisions of this disclaimer.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTA. CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

51397

31406



RBM
 OF ATLANTA
 7640 Roswell Road
 Atlanta, Georgia 30350
 (770) 390-0600

INVOICE

Mercedes-Benz

PAUL ISRINGHAUSEN
 229 EAST JEFFERSON
 SPRINGFIELD, IL 62701
 HOME: 404-229-8229 BUS: 800-790-1340

PAGE 5

SERVICE ADVISOR: 4*4 RONALD C TONA

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
199/275	1992	MERCEDES 503E	WDDEA36E1NB795271		92423/92693	TRONT
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	PAYMENT	INV. DATE
20JUL1992	12MAR98	19JUL1996	17:30 15SEP99		CASH	30SEP1999
R.O. OPENED		READY		OPTIONS: DLR:36712 ENG:11997412005031 PRN:737351		
				1)124036.1B.795271 2)RAD:9167 C977865		
11:05 02JUN99	10:06 30SEP99					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

K** THE CLIENT STATES THE MOTOR TEMP. IS RUNNING HIGHER THEN NORMAL. ADVISE

CAUSE: RSS
 CND UNABLE TO VERIFY/DUPLICATE AT THIS TIME.

412	CD	0.00			0.00	0.00	
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE K:	0.00

L** THERE IS A TAPPING IN THE MOTOR WHEN STARTED COLD. SEE HERB.
 CAUSE: RSS

07700	ENGINE LOWER OIL PAN, REPLACE	412	CC	1.40	99.05	99.05	
183090	ENGINE OIL FELDER HOUSING, R&R	412	CD	2.50	131.25	131.25	
18000001	REPLACE OIL PRESSURE VALVE INSIDE CANNISTER	412	CC	0.50	35.38	35.38	
STM	STEAM CLEANED ENGINE COMPARTMENT AND DRIVE TRAIN	412	CD	0.60	19.00	19.00	
147251	R&R AIR PUMP TO ACCESS CHAIN TENSIONER	412	CC	0.80	56.60	56.60	
057800	REPLACED CHAIN TENSIONER	412	CD	2.10	110.25	110.25	
1	119-050-17-11 CHAIN TIGHTER				187.00	187.00	
1	119-184-01-30 OIL PUMP VAL				12.65	12.65	
1	119-184-02-80 GASKET				5.50	5.50	
3	001-997-95-86 PLUG				4.84	4.84	
1	119-010-10-28 OIL PAN				104.50	104.50	
1	119-014-08-22 GASKET, CRANK				24.27	24.27	
1	00C908-010004 SCREW PIPE				4.20	4.20	
2	007603-010100 RING, GENERAL				0.60	0.60	
LUBE	9.0 QTS MOTOR OIL						
	C-NO				19.80	19.80	

STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS
<p>LIMITED WARRANTY</p> <p>The only warranties applying to the part(s) installed in accordance with this repair order are those that may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties including any implied warranty of merchantability or fitness for a particular purpose. No employee of the seller is authorized to alter or modify in any way any provisions of this disclaimer.</p>	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES	
	TOTAL CHARGES	
	LESS	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

61397

31406



7640 Roswell Road
Atlanta, Georgia 30350
(770) 390-0600

INVOICE

Mercedes-Benz

PAUL ISRINGHAUSEN
229 EAST JEFFERSON
SPRINGFIELD, IL 62701
HOME: 404-229-8229 BUS: 300-790-1340

PAGE 6

SERVICE ADVISOR: 414 RONALD C TONA

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
199/275	1992	MERCEDES 50CE	WDBEA36E1N379527		92423/92693	TRONT
DEL DATE	PROD DATE	WARR EXP	PROMISED	PC NO	PAYMENT	INV DATE
20 JUL 1992	2 MAR 98	19 JUL 1996	17:30 15 SEP 99		CASH	30 SEP 1999
R.O. OPENED	READY	OPTIONS: DLR:36112 ENG:11997412005031 TRM:737351 1)124036.1B.795271 2)RAD:9167 C9717865				
11:05 02 JUN 99	10:06 30 SEP 99					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
PARTS:	353	84	LABOR	451153	OTHER	19.80	TOTAL LINE L: 825.17

M** QUALITY CONTROL INSPECTED

QC305 BY BILL RIETER

305 I 0.00

(N/C)

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE M:	0.00
--------	------	--------	------	--------	------	---------------	------

SUBL FIXX-X-DENT - PO#15045

PO#414

LUBE 9.0 QTS. MOTOR OIL	CAD	165.00	165.00
	C-MC	19.80	19.80
LUBE 7.5 QTS. ATF	C-ATF	16.50	16.50

SUBL FUEL I (N/C)
CUSTOMER PAY ENVIRONMENTAL & RECYCLING COST PARTICIPATION FOR REPAIR CY 12.00

YOUR SATISFACTION IS OUR PRIMARY OBJECTIVE -
IF ANY PROBLEMS RECUR PLEASE CONTACT YOUR
SERVICE ADVISOR (INDICATED IN UPPER RIGHT
HAND CORNER OF INVOICE UNDER RBM LOGO) AT
390-0600 A.S.A.P.

***** THANK YOU FOR YOUR BUSINESS *****

R B M of Atlanta

STATEMENT OF DISCLAIMER

LIMITED WARRANTY

The only warranties applying to the part(s) installed in accordance with this repair order are those that may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties including any implied warranty of merchantability or fitness for a particular purpose. No employee of the seller is authorized to alter or modify in any way any provisions of this disclaimer.

DESCRIPTION	TOTALS
LABOR AMOUNT	2235.62
PARTS AMOUNT	1902.69
GAS, OIL, LUBE	67.95
SUBLET AMOUNT	165.00
MISC. CHARGES	12.00
TOTAL CHARGES	4377.26
LESS	0.00
SALES TAX	37.12
PLEASE PAY THIS AMOUNT	4514.38

CUSTOMER COPY

LAURENT DE GIVE & CO., LTD.
 MERCEDES-BENZ SERVICE
 688 TRABERT AVENUE, N.W. ATLANTA, GEORGIA
 (404) 351-2807 .30309

No. 12487

QTY.	DESCRIPTION OF PART	UNIT PRICE	PRICE
1	OIL FILTER KIT		15 50
1	OIL CAP		4 00
2	IGNITION ROTORS	650	130 00
1	CAN MB BRAKE FLUID		16 19
1	KT. FRI. DoorLock Servo		67 25
1	Screenwash Pump Gram.		1 00
1	Screenwash can		10 00
1	AUT. LUBE		1 32
1	TRANSMISSION DIRSTICK		24 00
4	BRAKE BLEEDER CAP	200	8 00
1	AIR CLEANER MOUNT		5 80
1	" " Nut ADAPTR		3 00
			289 06

NAME: Strinckhausen Imports DATE: 29 Feb 80

ADDRESS: SPRINGFIELD STATE: IL ZIP: 61801

CITY: SPRINGFIELD STATE: IL ZIP: 61801

SPEEDOMETER: 97.146 TYPE OR MODEL: E 60 (1.92 MB 500E) LICENSE NO.: WD8EA3E1NB79524

OPER. HOURS: 1.5

1.5 LUBRICATION SERVICE 65 00

1.5 Ignition evaluation → REPLACE Ignition Rotors De-corrode DIST CAPS. CHECK SPARK PLUGS for fouling 97 50

0.5 Renew BRAKE FLUID 32 50

1.7 REPLACE D.F. Door Lock Servo 110 50

1.0 MAKE OPERATIONAL SCREENWASH SYSTEM (SURE ARCADIS DEFECTIVE PUMP, ETC) 65 00

Evaluate RUNNING TEMP? *

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

I HEREBY AUTHORIZE THE APPROPRIATE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMITS TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE CAR OR TRUCK TO SECURE THE AMOUNT OF REPAIRS HERETO.

LUBRICANTS	PRICE	TOTAL LABOR	TOTAL PARTS	TOTAL FLUIDS	TOTAL AMOUNT
8 QTS. 15W40	17 00	468 00	289 06	17 00	795 48
QTS. AT FLUID					
90 W GEAR OIL					
TOTAL					

OBSERVATIONS: NOTES FINISH CHAIN RATTLE ON MOUNT

ENGINE START - WPT

* COOLANT TEMP ROUGHLY TOO HIGH → FAN

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

07/28/00 FRI 08:54 FAX 404 352 9129

Laurent de GIVE & CO

LAURENT DE GIVE & CO., LTD.
 MERCEDES-BENZ SERVICE
 568 TRABERT AVENUE, N.W. ATLANTA, GEORGIA
 (404) 351-2807 30309

file 995211
 MRP No. 12586

QTY	DESCRIPTION OF PART	UNIT PRICE	PRICE
1	Timing Chain	258.00	258.00
1	Pivoting Guide Rail	56.00	56.00
2	Fixed Guide Rail	11.86	23.72
1	Chain Tens Gasket	4.99	4.99
1	Leak Upper Guide Rail	18.12	18.12
1	Riskit "	17.11	17.11
2	Valve Cover Gasket Kit	40.25	80.50
2	Cam Adjuster Cover Spr.	5.00	10.00
1	Eng. Oil Pump	437.50	437.50
1	PAN GASKET	26.00	26.00
1	Oil Filtr. NSMG GASKET	6.50	6.50
1	Clearance Pkg, Preorder	4.10	4.10
1	P.S. Reservoir GSKT	21.00	21.00
2	M8 Sizer Ferris	13.50	27.00
1	LEFT. Rev. Box	9.82	9.82
1	RIGHT "	17.14	17.14
1	Cam. Pos. Indicator	136.50	136.50
1	" Selective Spacer	4.80	4.80
1	Ignition Rotor Driver	38.50	38.50
2	Cam. NOSH Seal RING	4.80	9.60
1	Coolant Pump over Flow Reseru.	36.75	36.75
1	RADIATOR NEW M8	470.00	470.00
1	Coolant Reservoir	78.75	78.75
1	" & Misc. Leaker	36.00	36.00
1	LOW OILK COVER	91.00	91.00
1	Surfing. BEAT EXCHANGER	175.73	175.73
		2095.13	2095.13

RESERVATIONS:

NAME: ISRINGHAUSEN IMPORTS
 ADDRESS:
 CITY: STATE: ZIP:
 BREEDOMETER: 99542
 TYPE OR MODEL: E60
 LICENSE NO.:
 SERIAL NO.: WDBE936E1
 NR 795 271

OPER. HOURS	DESCRIPTION	PRICE
	Access and Replace Timing Chain	585.00
	Pivoting Guide Rail of upper	
	Fixed Guide Rails	
	Investigate & Dial-Indicate Valve	585.00
	Timing with slotted gear Drivers	
	to Reuntech Oels. Specs.	
	DIAG INTAKE CAMSHAFT ADJUSTED RE-PLACE COVE SPRINGS WITH CATERS TYPE	325.00
	For Low Oil Pressure R&K Oil Filter	
	Adjusting Inspect' R&K Oil Pump	325.00
	Inspect' Replace	

I HEREBY AUTHORIZE THE APPROPRIATE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMITS TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR elsewhere FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANICAL WARRANTY IS HEREBY ACKNOWLEDGED ON ABOVE CAR OR TRUCK TO SECURE THE AMOUNT OF REPAIRS HERE TO.

X

Not responsible for loss or damage to cars or articles left in care in case of fire, theft, or any other cause beyond our control.

LUBRICANTS	PRICE	TOTAL LABOR	TOTAL PARTS	TOTAL FLUIDS	TOTAL AMOUNT
85 SYPHATIC	42.00	2145.00	2095.13	42.50	4482.63
OTS. AT FLUID					
90 W GEAR OIL					
TOTAL					4432.26

07/28/00

FRI 08:55 FAX 404 352 9129

Laurent de GIVE & CO

002 QTY

DESCRIPTION OF PART

UNIT PRICE

PRICE

NAME

LAURENT DE GIVE & CO., LTD.

ADDRESS

CITY

STATE

ZIP

MERCEDES-BENZ SERVICE

588 TRARBERT AVENUE, NW ATLANTA, GEORGIA

(404) 351-2807

30309

No. 12519

(2)

DATE

199

HOME PHONE

WORK PHONE

SPEEDOMETER

E 60

TYPE OR MODEL

LICENSE NO.

SERIAL NO.

OPER. HOURS

(Access and REPLACE timing chain)

FOUND coolant pump overflow

RESEALURE BROKEN, REPLACE

FOUND RADIATOR SUBSTANDARD CAP-

ACTIVY, REPLACE WITH MS.

FOUND excessive cyl. head Temp

on hot days, causing detonation

Regrad corrector's level -> FIT

Auxiliary heat exchanger

For rear of cyl. head cooling

Diagnose time for above

I HEREBY AUTHORIZE THE APPROPRIATE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE CAR OR TRUCK HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON ABOVE CAR OR TRUCK TO SECURE THE AMOUNT OF REPAIRS HEREIN.

X

RESERVATIONS:

LUBRICANTS

PRICE

O/S.

O/S. AT FLUID

90 W/ GEAR OIL

TOTAL

TOTAL LABOR

TOTAL PARTS

TOTAL FLUIDS

SUBLET REPAIRS

TAX

TOTAL AMOUNT

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

Chermark

12/14/00 THU 08:00 FAX 404 352 9129

Laurent de GIVE & CO

001

QTY.	DESCRIPTION OF PART	UNIT PRICE	PRICE	NAME	ADDRESS	CITY	STATE	ZIP	DATE	HOME PHONE	WORK PHONE
1	Wiper Inserts		9 36	ISRINGHAUSEN IMPORTS	568 TRABERT AVENUE, NW	ATLANTA	GEORGIA	30309	14 Dec 00		
1	TRANS GASKET SET		133 20								
1	Valve Body Seal Set		64 75								
1	TRANS. BAND B2		212 00								
1	TRANS FRONT PUMP		315 00								
5	Friction Disc K1	800	40 00								
5	" K2	8.00	40 00								
4	" B3	8.50	34 00								
1	Output SHAFT Nut		4 70								
1	TRANS Oil Filter		52 00								
1	K2 Thrust Washer		9 00								
1	B3 Auxiliary Spring		9 00								
1	Ac Thrust Cable Assy		169 75								
2	Outer Disc 50-26	2175	43 50								
2	51-26	2400	48 00								
1	32-26	2090	20 90								
1	34-26	2475	24 75								
3	36-21	1265	37 95								
1	47-26	1470	14 70								
2	49-26	1265	25 30								
1	GEAR Position Sw.		86 95								
6	FRONT Cover SCREW	300	18 00								
1	TORQUE Conv. PLATE		2 40								
1	K2 CUSTOM O RING		6 00								
			1421 21								

LAURENT DE GIVE & CO., LTD.
 MERCEDES-BENZ SERVICE
 568 TRABERT AVENUE, NW
 (404) 351-2807
 ATLANTA, GEORGIA
 30309

No. 12606

1. HEREBY AUTHORIZE THE APPROPRIATE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY AND REPAIRS TO BE DONE TO THE TRANSMISSION AND FRONT END COMPONENTS. I AM NOT PROVIDING ANY OTHER INFORMATION TO THE MECHANIC'S OFFICE. I AM NOT PROVIDING ANY OTHER INFORMATION TO THE MECHANIC'S OFFICE. I AM NOT PROVIDING ANY OTHER INFORMATION TO THE MECHANIC'S OFFICE.

OBSERVATIONS: TANDEM HYDRAULIC PUMP LEAKING
 ALTERNATOR V. NOISY, SHOULD BE REPAIRED

QTY.	DESCRIPTION	PRICE	TOTAL
1	Oil SYN	7.00	7.00
9	Oil SYN	63.00	63.00
	90 W GEAR OIL		
	TOTAL	70.00	70.00

Wouldn't go into Reverse
 When park was disengaged?
 Rebut Trans to work w/ mod engine



Mercedes-Benz

AUTHORIZED RETAILER

BMW

RENNTech



229 East Jefferson • P.O. Box 1028
SPRINGFIELD, IL 62705
(217) 528-2277

* ISRINGHAUSEN IMPORTS *
* YOUR BEST SOURCE FOR PARTS & ACCESSORIES *
* BMW MERCEDES-BENZ PORSCHE *

*For your convenience we accept
the following credits cards.*



CUSTOMER NO.	TAX EXEMPT NUMBER	CUST. P.O. NO.	SHIP VIA	PAY	SOLD BY	INVOICE DATE	INVOICE NO.
95271				OTHER	TIM H.	09/05/01	63234 MBI

B
I
L
L
T
O

S
H
I
P
T
O

PER PAUL ISY SEND TO
LARRY DEGIVE

QUANTITY	PART NUMBER / DESCRIPTION	BIN	LIST	NET	AMOUNT
0	129-421-17-12 BRAKE DISC	SP-ORD	121.00	86.21	172.42
0	129-421-18-12 BRAKE DISC	SP-ORD	121.00	86.21	172.42
1	002-420-15-20-05 SET OF BRAKE	39L05	79.00	56.25	56.25

Terms: Positively No Exchanges Without This Invoice. • No Refunds On Opened Packages Or Used Parts. • Items Returned Must Be In Original Packaging. • No Refunds On Special Orders. • No Refunds After 30 Days. • 20% Handling Charge On All Returned Items. • No Returns On Electrical Parts. • Refund On Purchases Paid By Check Are Refunded After Check Clears.

DISCLAIMER OF WARRANTIES

The Seller, hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the seller for any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages. In addition, expressly excluded is any dealer liability for defects pertaining to safety or performance, by way of "strict liability", negligence or otherwise.
In the event I fail to pay such amount due you, I agree that your costs of collection including court cost, and reasonable attorney's fees, shall be recoverable from me. I have read and with my signature agree to all of the terms and conditions in connection with this sale.

WE THANK YOU!

SUB-TOTAL

401.09

TAX
FREIGHT

0.00
0.00

PAY THIS AMOUNT

401.09

CUSTOMER SIGNATURE