



[Home](#)
[Close / AMG AMG E CLASS](#) [[Print](#)]

You guest [My BIDs](#) [logout](#)

Lot number Auction	Auction date	year	Engine CC	Chassis ID	Box of Modif. equipment	Colour	Mileage	Condition	Start	Sold for	Status
40152 USS Osaka	10.02.2012 [--:--]	1997	6000	210A60S	FA OTHERS AAC SR AW Leather PS PW		102000	4	70 000 ¥	0 ¥	

You guest
[Login into account](#)
 for make a bid

[Details of vehicle](#)

[Statistics by the model](#)

[Catalogue data](#)



Description

40152	車種 (車種入は任意) その他 自家用・レンタカー	排気量 6000 cc	型式 E-210A60S	評価点 4
	初年度登録年月 車名 9/10月メルセデスベンツ 4S AMG E 60	駆動方式 2WD		内装 B
車検	年 月	シフト FAT	装備品 AW P S P W TV ナビ E A B	セールスポイント ☆社外ナビ・ETC ☆アラーム・7-11-7Lガードシート ☆AMGマフラー・AW・EPO
走行	101,360 Km	冷房 AAC	新車保証手帳 (保証書付)	有・無
外色	ダークブルー	カラーNo.	197	内装色
燃料	ガソリン・軽油	輸入区分	ハンドル	左・右
リサイクル預託金	17,640円 預託済み	乗車定員	5人	登録No.
		車台No.	WDB2100721A475157	シリアルNo.

※ご記入の際はボールペンで強く記入下さい。

◎注意事項 (修復・不具合箇所および状態等)
 *ヤ(L)PW不良 @原動機型式 (AMG 60)
 エンジン車庫
 ◎検査員報告
 窓ガラス不良
 ホンネトグシ不良
 ホルホル
 シフトレバー
 ドーム内装汚れ
 ディスク汚れ
 転口、ホック不良

長さ 480 cm 幅 180 cm 高さ 141 cm (車検表上の寸法)

- A1 Small Scratch
- A2 Scratch
- A3 Big Scratch
- E1 Few Dimples
- E2 Several Dimples
- E3 Many Dimples
- U1 Small Dent
- U2 Dent
- U3 Big Dent
- W1 Repair Mark/Wave (hardly detectable)
- W2 Repair Mark/Wave
- W3 Obvious Repair Mark/Wave (needs to be repainted)
- S1 Rust
- S2 Heavy Rust
- C1 Corrosion
- C2 Heavy Corrosion
- X Need to be replaced
- XX Replaced
- B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)
- B2 Big Distortion on (radiator) core support or back panel
- Y1 Small Hole or Crack
- Y2 Hole or Crack
- Y3 Big Hole or Crack
- X1 Small Crack on Windshield (approximately 1cm)
- R Repaired Crack on Windshield
- RX Repaired Crack on Windshield (needs to be replaced)
- X Crack on Windshield (needs to be replaced)