


ENGINE 601, 602, 603

Damage code	Cause	Remedy	
None	Cylinder head porosity in the area of the front oil gallery for the oil supply of the first camshaft bearing and the hydraulic valve tappets	Replace cylinder head. Clean cooling system  This porosity can not always be detected when pressure testing the cylinder head	ra20006010015x